



CERTIFICATE.


The inspection of School Building of Vijay Memorial Sr. Sec. School, VPO. Indora, Tehsil Indora (HP) situated on Khasra No. 4826/1117, 5366/1125/1, 1126, 4830/1130, 4832/1131, 4843/1140, 1144, 1145, 1124, 1123, 1125, 5365/ 1125/1, and Khotuni No. 1924, 363, 364, 448, 1290, 1597, 1635, 1200, 1291, 1292, 1201, 1682, 1597, 1718, 1636 has been conducted by the Junior Engineer/ Assistant Engineer, Sub Division, HP. PWD. Badukhar. On the basis of their inspection report, it has been found that no Earthquakes resistant norms have been adopted for the construction of School building. No structural drawings approved by the competent Govt. agency were produced by the School authority. The structure of the building is a non-Engineering structure. Hence, the structural safety of building can't be ensured specially from Earthquake point of view. This Department will not responsible for any type of loss of life and property etc., if this structure fails under any circumstances.

However, as per visual inspection, the building appears to be safe and accordingly, the Building Safety Certificate is being issued by this Department from 01.04.2026 to 31.03.2027. This Department could not access the structural safety of said building as the same was not constructed under the supervision of this Department.

Place :- Indora.


Junior Engineer,
Sub Division, HP.PWD.
Badukhar.


Assistant Engineer,
Sub Division, HP.PWD.
Badukhar


Executive Engineer,
Indora Division, HP.PWD.
Indora
09/26/2026

